

East Worlington Parish Hall Newsletter



Render and Window Project Edition 06 – 17 August 2018

Repaired Window Installed

The second repaired window was installed during this week. Haydons of South Molton were the firm that undertook the repair. The rotten timber, which was mainly the bottom rail rising up the jambs and mullions, was removed. New timber was profiled to match exactly the timber that was removed. This new timber was joined to the existing frame by using scarf joints.





The bottom rail showing the scarf joint on the jamb





Header joint with jamb

Fitting the repaired window and the window in situ



Supported by

The National Lottery®

through the Heritage Lottery Fund



Render and Window Project

North Elevation - Finish Coat Applied







West Elevation – Stone Wall Pointing Finished













http://www.eastworlingtonparishhall.btck.co.uk/ https://www.facebook.com/EastWorlingtonParishHall/ https://twitter.com/EWPHHeritage http://ewparishhall.blogspot.co.uk/

Key details:

For **bookings** please contact: **Lorna Manton**

Tel: 01884 860657

Email: bookings@ewph.uk

Please contact us to discuss your particular requirements

